

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/12 : CIA-RDP81B00879R000500080146-2 No. 11543

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 3-8-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO. S.O. NO.			
	DRAWING NO. AND DESCRIPTION									QUANTITY ACCEPTED	REJECTED	REMARKS
6	322		5	0	21							
738304 Gear Shaft Assy										6	✓	
IP# 704722												
To supersede Rec. Insp. report #11522												

RECEIVED
BY HMC-106INSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11555

RECEIVED FROM

DATE REC'D. 3-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO. S.O. NO.			
	DRAWING NO. AND DESCRIPTION									QUANTITY ACCEPTED	REJECTED	REMARKS
63	322		015	0	21							
734225-1 Flange Assy Spool										63		
IP# 704732												

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080146-2

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.